




Dimensional Drawing



Schematic



Rendering



PCV-08F-08F-13-023-V

PCV Pneumatic service check valve		Model Code
08F	1/2" NPT female	Inlet Connection
08F	1/2" NPT female	Outlet Connection
13	13 bar	Working Pressure
023	0.023 bar nominal	Cracking Pressure
V	Viton -20°C to +180°C	O-ring Material
PCV -08F -08F -13 -023 -V		Model Number

This is a bespoke datasheet. For further details on the complete range, please refer to catalogue:
Check Valve Models HCV, PCV, SCV, DCV & EFCV2

Accuracy of information
We take care to ensure that product information in this catalogue is reasonably accurate and up-to-date. However, our products are continually developed and updated so to ensure accurate and up-to-date information please refer to the product catalogue issue list on our web site or contact a member of our sales team.

When selecting a product, the applicable operating system design must be considered to ensure safe use. The products function, material compatibility, adequate ratings, correct installation, operation and maintenance are the responsibilities of the system designer and user.

Quality Assurance
All Bifold products are manufactured to a most stringent QA programme to ensure that every product will give optimum performance and reliability. We are third party certified to BS EN ISO 9001:2008. Functional test certificate, letter of conformity and copies of original mill certificates, providing total traceability are available on request, to BS EN 10204 3.1 where available. We reserve the right to make changes to the specifications and design etc., without prior notice.